

Donald E. Duthaler

From: Donald E. Duthaler
Sent: Tuesday, April 22, 2008 2:59 PM
To: 'Steve Hoats'
Subject: Cortlandt, NY drum
Attachments: sketch showing drum.pdf; IMG_1848.JPG

Steve

As discussed, the attached sketch and photo show the location of the old drum located in the rear of the building at 510-534 Furnace Dock Rd in Cortlandt. The photo does not show it, but the other side of the drum has deteriorated and a good portion of the side of the drum has completely rusted away. There is some soil in the drum, but I do not believe that it is above the existing ground level. We have no idea on the history of the drum or its contents.

Please remove and properly dispose the drum and any soil which is in the drum when EWWI is out at the site tomorrow. Please advise me of the conditions under the drum. Please smooth this area so as to not leave a trip hazard after the drum is removed.

Please call with any questions.

Thanks,
Don



FOR CONSTRUCTION
DETAILS SEE
DWGS C-2 & C-3

